

# Oil Field Environmental Incident Summary

**Incident:** 20150621140200      **Date/Time of Notice:** 06/21/2015 14:02

**Responsible Party:** EOG RESOURCES, INC.

**Well Operator:** EOG RESOURCES, INC.

**Well Name:** LIBERTY 8-01H

**Field Name:** PARSHALL

**Well File #:** 18365

**Date Incident:** 6/20/2015      **Time Incident:** 13:50

**Facility ID Number:**

**County:** MOUNTRAIL

**Twp:** 151

**Rng:** 91

**Sec:** 1

**Qtr:** NW NW

**Location Description:** Hayland area to the east of the location, 40 ft. long by 30 ft. wide

**Submitted By:** Keith Kallberg

**Received By:**

**Contact Person:** Keith Kallberg  
600 17TH ST STE 1000N  
DENVER, CO 80202

**General Land Use:** Other - Described Above

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Other

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	5	Gallons	5	Gallons	5	gallons

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 7/14/2015

**Clean Up Concluded:** 6/21/2015

**Risk Evaluation:**

N/A

**Areal Extent:**

Hayland area to the east of the location, 40 ft. long by 30 ft. wide

**Potential Environmental Impacts:**

N/A

**Action Taken or Planned:**

The work over rig just had the one upset. Cleanup crew was called in and the area was clipped, raked and removed.

**Wastes Disposal Location:** To be determined.

**Agencies Involved:** TAT and MHA

**Updates**

---

**Date:** 6/22/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to workover rig upset, impacted hayland area off location, according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.